THALES

ID No. 787	Product/Process Change Notification	Date 12.11.2020
Product	Ordering Code	
EXS82-W Rel.1.1	L30960-N6200-A110	
EXS62-W Rel.1.1	L30960-N6250-A110	

EXS82-W Rel.1.1	L30960-N6200-A110 L30960-N6250-A110	
EXS62-W Rel.1.1		
Pagan of Change		
Reason of Change:		
☐ Technical requirement	☐ Change of production process/logistical changes	
☐ Customer requirement	Location of production moved	
Quality improvement	Other:	
Description of change:	Thales will introduce a new firmware that consider an improved Cinterion® loT Suite Service Agent - including FOTA update via loT Suite.	
	SW Revision is same with previous one: 01.100	
	The application revision string of ARN is changed from 01.000.08 to 01.000.11	
	This application related change is not approval relevant.	
Schedule details:	[Schedule of Introduction]	
Availability of SW for evaluation:	CW46/2020	
Availability of modules ex THALES DIS AIS Deutschland warehouse:	CW01/2021	
Timing note:	If THALES DIS AIS Deutschland GmbH does not receive a notification to the contrary within a period of 6 weeks, THALES DIS AIS Deutschland GmbH assumes that the customer agrees to the change.	
Quality assurance measurements:	The new version fulfils all internal test requirements according to our Quality Management process and philosophy.	
Attachments:		
	2020 18.11.2020	
7/ Jan	i My Com	

Product Lifecycle Manager

Vice President Quality Management Signed by: ZHANG Kai Signed by: ERDMANN Joerg